

SERVICE INSTRUCTION 02/11

Publication Ref. Number: 099

Date: 19/Jun/2011

SUBJECT

Cylinder strapping.

CATEGORY

Advisory.

APPLICABILITY

Large Ultramagic baskets with Single or Double T Type partition

COMPLIANCE


Achieve at pre-flight inspection

BACKGROUND

It has been found that repeated incorrect strapping of cylinders could lead to a premature distortion of the basket woven wall.

INSTRUCTIONS

To prevent this possibility, check that the cylinder straps are installed according to the following scheme:



In doubt contact your Ultramagic dealer or the factory.


Josep M Lladó Costa

DOA Head – Aeronautical Engineer

The content of this document has been approved under the privilege of the Design Organisation Approval nr. EASA.21J.351

Ultramagic, S.A.

Aeròdrom **Gral. Vives** Igualada-Òdena
Ap. Correus (P.O. Box): 171 – 08700 Igualada (BCN) Spain
Tel.: +34 93 804 22 02 – Fax: +34 93 803 56 04
e-mail: admin@ultramagic.com